Maintenance Work Order Request



The content will be content																							
West		Shift	Date of Request	Email	Requestor Phone Prior	v	Requested Work	Assigned to	Work Started Date	Progress	Category of Work	Work Completed Date	Work Completed b	y Maintenance Notes	Hours Worked	OF	Materials & Supplies	Cost	Labor Cost	Material Cost	Total Cost	Completed	Princey
1	0709 24 8		05/06/25	mark hoffman@toledo.oh.gov																			
				*			Water has collected on the floors in both offices, and the lounge room. I'm not sure if drains are clogged on the parapet wall on the host of the building or if its a different type of not draining issue. Carpets in all 2 rooms are saburated.																
1	1797	•	05/06/25	ambony santiago@ssiedo.ch.go v	4199362437 Urger		Plymovent vert for Rescue 7 is not securing the Rescue. We backed the engine in and sled to connect the plymovent for the Rescue onto the engine and it would not																
Marcha M	0796		05/06/25	cary cossett@toledo.ch.cov	4190509542 Urger		magnets and some present appeared to be covered in rust. overhead bay door on the Hess Rd side would not close. It would get about a foot									-							
Marcha M			05/06/25	Smothy furey@taledo.ch.gov	419 260-2512 Lirger		from the floor then go back up. middle toilet in mens looker room - flush toilet water worth shut off-									_							_
1	orsa 24 /		05/05/25	john schnosberger@toledo.oh.g ov	Lirger		Toilet in watch room will not flush															-	
1			05/04/25	Tammy Chrightoledo.ch.gov	419-936-2416 Routi		Need multiple 4" foursecent small light bulbs replaced. 16"s does not have a ladder to complete this task.																
1				stephen drouillard@toledo.ch.p ov	4199363317 Urger		Water spigot leaking in the apparatus bay. Close to the officer side of engine 17. This leak seems to go 24/7 and often leaves a puddle next to our fire gear by the engine.																
1							Station 13 has an art invasion going on. We need several ant traps and spray.																
1	•						Countspouts on North side of building (the alley between station at the flar next door), are smasted and need repairhiplacing. Looks like care parking in alley could have potentially hit downspouts.															U	
			04/29/25	gregory xxumigala@toledo.ch.g ov	419-936-2423 Lirger		Pole light in parking lot (closest to Erie Street), does not work. Needs servicing.																
Mathematical Content			04/29/25	matthew shiping toleds on gov	4199362425 Lirger			Carl Wilson	04/29/25	Completed	HVAC	042925										<u> </u>	
No.			049895	mathew shiple@toledo.oh.gov	419-270-1507 (cell) 4199362425 Lirger											-						— H	
				kyle wiley@toledo.ch.gov	419-467-2463 Urger		Shower head in women's locker room has a slow drip.																
Mathematical Content	1773	•	049495	Jeff wheeler@toleds.ch.gov		t	Significant amount of arts in the engine officer's room																
			049495	kristin tanner@toledo.ch.gov	419-356-8287 Urger		AC out to offices and to lounge on du 2 this has been fixed this morning but this is the followup request for the Work-thank you. The morning in China and the Work thank you.	Carl Wison		Completed	HVAC	049495											
No.			040105	pov pov michael moutatifficiado ob or	Cart Sometalt Lines		Instructing in Ordicar's soon can not be set to "Local stoder on the stodes. Only least and OPE are options, the Cool option is no longer present on the display. The second floor man's room shower in leaking again. It is coming draw hatever	Carl Wilson		Completed	Diumbino					-							
							the side door to the patio and the kitchen table. The sink handle in the men's bathroom is broke									-							_
Mathematical Content		•	04/15/25	michael green@toleds.oh.gov	419-450-1297 Routi		Gate to the parking lot drags on the pavement when swinging open or closed.																
Mathematical Content						t	Helio fine sir, when arriving today, and TPO officer stated he responds 3-4 times a week at HO for burglary alarm, and appeared flustrated. Are you able to look at alarm history to verify.																
Mathematical Math						ency	Refrigerator stop working.			Completed	Electrical											☑	
Mathematical Content				Smothy furey@taledo.ch.gov			Time to shut down the radiator for the Season-Thanks. Sinn sink more door is broken. The closer is broken from Itself. Door stress man.	Carl Wison Mark Drinns	04/10/05	Completed	HVAC BAG	06Y005				-			-				
1						-	and interferes with plymo and ambulance. Need plymovent for chief car fixed, its hanging off the pipe	Mark Briggs		Completed	BAG					-							
Mathematical Content	6762			hally bennet@toleds ah.gov			Far right sink in mens looker room needs a new faucet. Knob is corroded and broken off.																
1							Plymovent vent for Rescue 7 is not securing the Rescue																
							spigot needs regisced on rear app floor between water rescue and MS. We are unable to turn off the water with the spigot and it has a very steady leak.																
1							bace entry door frame is coming out of place when opening and closing the door, the bobs inside the frame to the wall are spinning freely and the caulk around the frame is no longer there.	Mark Briggs	061035	Completed	w&G	041025										✓	
1			04/04/25	Brian Matuszynski@toledo.oh.g ov	419-490-7354 Litger																		
Mathematical Content			04/03/25	cansel evanu@toledo.oh.gov	4193603167 Urger		rruck 5 pymo-drags on ground - wont stay attached to rig: just falls to the ground. Inoperable.																
Mathematical Content	•			*			officers mt. There appear to be wet coaling ties also. This is a new issue, I don't recall there ever being water there. Some kind of roof leak.																
March Marc			04/03/25	weeley bombrys@toledo.ch.gov	419030344 David		The phymovent never turns off and will run continuously accounts from health work street	Carl Wilson	040205	Completed	Plymov	041005		Soliton and riseased universities								<u>~</u>	
No.	0753 47 1		03/29/25	jeff wheeler@toledo.ch.gov	4194646516 Routi		The officer's light in the shower is out		Jeonab					-g1 and common up with WES									_
1	6752 4				419-351-3712 Routi		Mens locker room is in need of 2 tolet paper holders. One is missing and the one																
1							door knob on officers bathroom not working property. outside knob stuck and will																
1	1.0						noted that the plymovent for the engine cycles through repeatedly before shutting off after the engine leaves, its at least 4-5 times that it comes on and off before featly stopping. Is this the normal cycle of it is hard																
							The floor drain under MM is not working																
	7 7	•	03/26/25	anthony santiago@toledo.oh.go V	4199362437 Urger		Leaking urinal in the men's looker room. There are several ceiling tiles in the kitchen that are water stained. Michride advised there were extra tiles ordered. Can aome of the ciles in the skitchen be replaced as the brown outded acost I will	Mark Briggs	041025	Completed	Plumbing	041025		Re built the sloan valve									
	0747 44		09/25/25	Firestation 14c@toledo.oh.gov	4199301414 Rousi		disgusting. Thank You Flushing system on tollet in men's upstains bathroom is broken.		-							-			-				_
Mathematical Content			09/25/25	Smothy furey@tsieds ah gov	419 260-2512 Routi		need halyard replaced on flaggole. Halyard which derives from the Middle English halier "roce to hauf with". If you provide a large spool of roce we can get it strung	Mark Briggs	09/27/25	Completed	BAG	092705										2	
Mathematical Content	ores 18 /	Α	03/24/25	ryan parquette@toledo.oh.gov	station 19 Routi		back up with TLS. Thanks would like to request the snaking of the Soor drain located under E18 bay. Also	Mark Briggs	040225	Completed	Plumbing	040205				_						▽	_
							the cast head area, which is return dropping debris onto the area. It appears that it has been addressed before.																
	21 5		03/24/25	ian downing@toledo.oh.gov	4192614492 Urger	t	The back door to the station only has a deadbolt so it a crew member is trying to leave the station (e.g., after their shift is over but when both rigs are out on suns), the station consents can't has second records; benefities a new handle that has a																
Mathematical Content	6743 24 /		099495	ian downing@toledo.oh.gov	4192914492 Lirger		lock built in would allow it to be locked on the way out of the station. Approximately a dozen carpet squares in the television room have become ungleed																
					419-301-C784 Drum				030405	Companie	Liedical			installed new cord end		-							_
							valve the entire time the boiler is switched on. Range extender needed for TL4 bay door. Darkinson service personnel that were	Mark Briggs	040105	Completed	RAG	060105				-							_
1	araa 12 '	0	03/21/25	kyle wiley@toledo.ch.gov	419-467-2463 Routi																		
							pressure and flow as well. Garage Door 6 on Chase St. Side of Station. Garage will not open when pressure	Mark Briggs	032525	Completed	RAG	090505		Darkinson has been notified and will be out today to		-							
1							button on wall. No lights on the eyelet indicators. No tripped breakers at breaker box as well. M. Briggs contacted by phone and stopping out today.	-															
1		•	09/19/95				New water lease in commonystorm set right Stellow 11 has a least annewhere in nivers sustain. Sustain is kinkler in resolvable.	Intern Keiser		Consisted				I have been out to look at this leak and will look into- getting some of these leaks looked at.									
1			03/18/25	Smothy Azev@tuledo.ch.gov	4192902512 Urger		TLS given has a hole where it conects to the elbow	Joseph Kekes	032425	Completed	RAG	090405		replace upper and lower hoses		-			-				
		•					the medic unit garage door is not closing consistently, it seems to hit bottom hard and harms an object and salars in falls your. It is immediated and report find a	Mark Briggs	03/04/25	Completed	BAG												
Math		-					pattern. Investigation of ant infestation in kitchen, proper steps taken to resolve the issue	Mark Briggs		Completed				Ant trace have been dropped off.		-					\$20.00		
1	e731 19 /		03/15/25	frank villameal@toledo.oh.gov	4193433524 Lirger		Dryer will not heat up. It will sumble but it is not heating up	Joseph Kekes		Completed				This unit is working now the capt, will keep an eye on a									
	1729 3 4	Α .	03/15/25	michael rometadt@toledo.oh.go v	Capt Rometadt Urger	t	A roach was found in the kitchen area just outside the watch desk. If possible could the station get sprayed for maches and possibly bed bugs	Mark Briggs	031935	Waiting on Contractor	BAG	091905		This station has a regular contract for an exterminator to spray i will notify him to see if we can get an									
No.	1728 14 1		09/13/25	colin desaintsictor@toledo.oh.g	4193444887 Routi		Floor drain on the apparatus floor inn't draining well, the garden hose was left filing	Mark Briggs	031305	Needs to go out for Bid	Plumbing			I had speedy Drain cleaning out and they were unable									
Part														company to cut the floor and replace the drain pipe. I have called 2 contractors waiting on calls back.									
1	J724 6 /	•	03/08/25	Smothy furey@toledo.ch.gov	419 260-2512 Lirger	t	Would like to get a new exterior door for Fire Station 5 Kitchen-currently the glass is cracked (6 floorths) which will need replaced but the door has many glapsiplor and.	Mark Briggs	031105	Walting on Contractor				I have reached out to a contractor to look at this door, to determine the need of replacement and cost. As soon as I get three quote I will out in for a P.O. This									
1														was done for the glass but I think the door needs to be replaced.									
1							the flat roof-standing water is sitting on the roof-I would think the drain should be working following new roof placed on Station	Joseph Kekes		Adknowledged Work Circler													
1							Toilet upstairs needs new flush handle lever. Existing lever corroded and unusable.	Joseph Kekes		Acknowledged Work Order													
1							The officers bathroom has that sewer smell again, the trap may need drained or pumped out or what ev.	Joseph Kekes		Completed		0218/25		The Grease traps were full, they were pumped out							\$624.00		
1			WF1895				heating unit at fireshop exhaust gipe rusted apart allowing furnes into the building.	Carl Wilson	-	Acknowledged Work Order	HVAC					-		-					
1			01/29/25	john achnosberger@toledo.oh.g	Routi		Repair of fence along the pask (north side of property). Third section in from the sharf in horizon.	Joseph Kekes		Acknowledged Work Order	BAG												-
			010005	joseph.camerato@roledo.chio.g	4193413034		heat out in kitchen set at 72 temp in room 63	Carl Wilson, Mark Briggs	01/17/05	Walting on parts	HVAC			This is a computer issuer we are unable to access this computer we called an outside contractor in and these									
														have said that it is a relay and an outside temp sensor that are bad. They have parts on order and will repair as soon as the parts come in.									
1							Outlet nearest the door from the watch desk to the bay is not functioning. Unable to find a tripped breaker and reset button did not change status.	Joseph Kekes	01/21/25	Acknowledged Work Order	Electrical												
1				gregory szumigala@toledo.ch.g			Exhaust vent in app floor bathroom is not functioning. needs repaired replaced.	Carl Wilson		Acknowledged Work Order	HVAC												
March Marc							These appears to be a water leak coming from the mens looker room. The rug by the skibline door leading to the patio had a puddle of leater on it this morning. Next take to Scrott libraries work years down	Joseph Kekes		Acknowledged Work Order	Humbing			On going issue when crews take showers. unable to find soutce of leak still working on it.									
No.			010425	robert thomas@tol.oh.gov	419-496-2017 Urger					Acknowledged Work Order	BAG												_
1							representation from the age of the busidest be supplied if there is lead paint. If attach photos. This is in the sleeping areas, so members are being exposed to dust, chips, etc.																
1			01/02/25		Routi		Hand scap dispenser in male frefighters looker room is broken and needs replaced	Joseph Kekes		Acknowledged Work Order	BAG												
Part		۰					Plug cover and baseplate in TV room need replaced. Baseplate is broken and will not longer haid switch cover.	Stani Briggs Carl Wilson		Acknowledged Work Order													
1							please. Station 12 keypad on gate is not working. Gate will open and dose when however.	Mark Briggs	-	Advice/edged Work Order	_					-			-	-			_
140	-						pressed or kelfy card is used. However, Reypad to purich in code is not working. Card from bldg maintenance was out here to address a mod leak and stated he would reach out to vendor to have them take care of the keypad.	-															
1							pasking for Flood light needs replaced_west light out	Carl Wilson		Acknowledged Work Order													
1										Acknowledged Work Order Acknowledged Work Order													
1	"																						
1985 1987 1988 1989			11/30/24	Smothy furey@toledo.ch.gov	419 260-2512 Linger		Majority of the app floor lights are burned out-we discussed switching over all lighting on app floor to LED. We will need to get this on the schedule - more lights.	Joseph Kekes		Acknowledged Work Order												0	
Company Comp	1658 9 1		110604	christopher burns@toledo.oh.go	419-899-1395 Emer	pency	are burned out than are operational. Thanks Vehicle vanishins at Station 9. TPD contacted and investigated (RSe 047483-34). Decuation interced residue for interfer. **The Contact of the Contact of t	Carl Wilson, Joseph Kekes		Acknowledged Work Order												-	-
1				*			light towers. Also, the passing or give his a substantial gap at his octors and is not totally securing our vehicles.																
1			110104	john schnorberger@toledo.oh.g ov hov/likt tilfkome*******	Routi		Casing ager at back door flickering	Carl Wilson		Acknowledged Work Order													
1							repair to be described as water mitigates the top layer. Currently a hand sized area.	man wings		ALL LA BOOK OF WORK CITORY													
A		•	11/07/24	anthony santiago@toledo.oh.go V			Shower head leaking in men's looker room. It appears the toilet is still leaking water	Carl Wilson		Acknowledged Work Order				A shut off valve was placed a the shower head to see if that would stop the leak, the leak persists.									
				tmothy furey@toledo.ch.gov	419 260-2512 Linger		Please set some Rat traps in exterior rear of Station-Multiple Rats in grill and surrounding area.	Mark Briggs	11/07/24	Completed	M&G Daint	11/07/04						_					
1							 rever museum mutges requests to have approach and app floor painted with white stripe to assist backing efforts. If we have access to stripe parking lot that would be a huge bonus (justice is LFRIs has a skentalic). 	mand striggs		ALL Corrected Work Order	rant												
3 P 00150 (and managination day of contracting the contraction of the							Garden hose on app floor near hallway. (Next to medic unit -front of station). Leaks	Joseph Kekes		Acknowledged Work Order				This hose real is leaking internally needs to be replaced					\$25.00				
Address 7 Backson Anthropological production Anthropological pro	1428 3 I		08/15/24	daniel evanu@toledo.oh.gov	4193603197 Lirger		Showers in men's lower room is leaking through the ceiling in the kitchen near the door to the patio along bush street. A shift tree shower frimings a 5	Carl Wilson, Joseph Kekes, Mark Bricos	081694	Completed	Plumbing			This is an ongoing problem we are unable to find the source of this least will confirm to fiv.	1							0	
2 200 200 Antique principal Elifestic Collection Principal Principal Elifestic Collection Principal Principal Elifestic Collection Principal							change and \$\overline{a}\$ shift noticed active water coming through the celling a short time later. A bucket was placed under to catch water. Not actively leaking while shower not in use.	-															
1940 S B 0000 percent gradients and percent from the contract contract to the square of the contract contract contract to the square of the contract contract contract to the square of the contract cont				Anthony santago@ Toledo ch gov		10	Paint of front lettered panels and upstains hallway, offices, and donns	Mark Briggs															
	•	•	08/06/24	jason.earp@toledo.ch.gov			Glass on back door into kitchen cracked, needs to be replaced.			Needs to go out for Bid				Getting bids on replacement glass. \$113.54 still waiting on one more bid									
1 In the contract of the contr	•						Need to replace multiple florescent lights (burned out) on App floor- be great to have aclasor lift.	Joseph Kekes		Adknowledged Work Order				This station is next on the list to retro fit to LED lights. As time will allow.									
	10	•	04/21/24	brandon walton@toledo.oh.gov	4190994490 Urger		App toor neater box at ceiling, closest to lockersoom, fan motor sound has increased and sounds like it needs repaired or replaced.	Carl Wilson		wasing on parts	HVAC			this is a very difficult part to find still working on parts.				_					
	\rightarrow																	-					-
																							_