

Toledo Fire&Rescue Department

BUILDING MAINTENANCE BUREAU 545 North Huron Street Toledo, OH 43604 419-936-2462



2022 BUDGET REQUESTS BUILDING MAINTENANCE BUREAU

2022 – CIP – (\$1,133,200 total spend, not including lines 23 or 31) -Lines 23 and 31 are variable cost from \$750,000 to \$2.1 million-

1. Station 13 – Upgrade (3) boilers and controls	\$40,000 estimate
2. As Needed – Replace plymovent motor and fan	\$3,200 Hastings current price
3. Station 14 – Replace men's restroom	\$15,000 estimate
4. Station 5 – Install safety bollards – overhead doors	\$20,000 estimate
5. Station 5 – Install AC for the station	\$50,000 estimate (GEM)
Eliminating window AC throughout the station	
6. Station 19 – Finish kitchen upgrade	\$15,000 estimate
(If not complete in 2021)	
7. Commercial stoves – 2 (station to be determined)	\$5,000 estimate for 2
8. Station 21 – Finish replacing 15 windows	\$30,000 estimate
9. Station 5 – Replace roof - Tear off	\$1000,000 estimate
10. Station 14 – Replace kitchen	\$30,000 estimate
11. Station 5 – Replace kitchen	\$30,000 estimate
12. Station 18 – Replace kitchen	\$30,000 estimate
 Station 24 – apparatus floor heat – Unit heaters 	\$20,000 estimate
14. Station 17 – Larger extractor for double company	\$15,000 estimate/ quote Belenky
15. (2) new extractors – upgrade 20+ year old units	\$20,000 estimate
Stations to be determined	
16. Station 24 – Prep and resurface roof	\$40,000 estimate
17. Station 24 – Upgrade apparatus floor lighting	\$5,000 estimate
 Station 11 – Approach concrete work 	\$30,000 estimate
19. Station 4 – Kitchen windows/ sliders	\$40,000 estimate
20. Station 16 – Approach replacement	\$40,000 estimate
21. Station 13 – Replace approach and parking lot	\$45,000 quote from SB&H
22. Card Readers for remaining 12 buildings	\$60,000 Habitec – state contract
23. Training Bureau – New burn building	\$350,000 to \$750,000 – quote Bullex
24. Station 9 – Replace kitchen	\$30,000 estimate
25. Station 17 – Replace windows	\$30,000 estimate
26. Station 23 – Enlarge parking lot	\$15,000 estimate
27. Station 25 – Repave parking lot	\$5,000 estimate S.B. & H.
28. Imlay – Remove perimeter fence/ install new	\$50,000 Marleau Hercules and estimate
With new gates and operators.	



Toledo Fire&Rescue Department

BUILDING MAINTENANCE BUREAU 545 North Huron Street Toledo, OH 43604 419-936-2462



- 29. Imlay Electric work for operators
- 30. Imlay Asphalt the parking lot

\$20,000 estimate \$300,000 estimate

31. The Plymovent exhaust system is 25 + years old and would benefit by being upgraded, a quote from Hastings Energy (Ohio Plymovent supplier) to replace the entire system would be \$1.4 million dollars. An alternative would be to upgrade the lower hose and nozzles (these items are where the new technology upgrades have been made) would be \$400,000 for all 72 plymovent drops we have in all of our buildings. The "bright green" represents 2 motor/ fan assemblies being replaced, we have replaced 6 assemblies in the last 3 years from the general fund budget due to not having CIP. These motors are a part of the 25+ year old system that needs replaced.

 ${\bf 2023}$ - Budget will be the remainder of what cannot be complete in 2020 and any other priority item that comes up.

2022 - GENERAL FUND - (\$100,000 Total spend)

- The average spend from the General Fund budget over the last (7) years has been \$46,000. This includes 2 years when the spending was either completely shut off or suspended for 5-6 months in each of the 2 years. This is an average of \$2,090 per building (22 buildings) for the year. 18 of the 22 buildings are "lived-in" by firefighters 24/7/365. I believe starting with \$75,000 would be fair, as long as we also get CIP money.
- Overhead door repairs (general fund) \$25,000 is needed for overhead door repairs from an outside contractor. Even with our preventative maintenance program being performed by TFRD building maintenance personnel we averaged \$20,723 in overhead door repairs over the past (7) years, (2) years were over \$28,000.

Submitted by,

Tom Kalucki – Captain Toledo Fire and Rescue Department Building Maintenance Bureau