

Addendum B = Out-of-Service Report

EXTRA APPARATUS REPORT				
Date	9/24/2025	Shift		
Rig #	Home Station	Current Location	Status	Comments
Extra Battalion Vehicles				
C863	Shop	Station 12	available	Battalion 4 when needed
Extra Medics				No Medic Units
M900	Shop	M4	I/S	repairs (999)
M903	Shop	Shop	O/S	Turbo / nox sensor parts ordered
M904	Shop	shop	O/S	ABS sendor EGR parts ordered
M911	Shop	M19	I/S	park brake issue (990)
M992	Shop	M18	I/S	repairs
M993	Shop	Shop	O/S	at delaership
M995	Shop	Shop	O/S	cab floor issue
M999	M4	shop	O/S	broken body mount issue

EXTRA APPARATUS REPORT				
Date	9/19/2025	Shift		
Rig #	Home Station	Current Location	Status	Comments
Extra Battalion Vehicles				
C863	Shop	Station 12	available	Battalion 4 when needed
Extra Medics				No Medic Units
M900	Shop	Shop	O/S	Repairs
M903	Shop	Shop	O/S	air brake leak
M904	Shop	Shop	O/S	Repairs
M911	Shop	M19	I/S	park brake issue (990)
M995	Shop	Shop	O/S	cab floor issue

M993	Shop	Shop	O/S	at delaership
M992	Shop	M18	I/S	Repairs
EXTRA APPARATUS REPORT				
Date	9/18/2025	Shift		Comments
Rig #	Home Station	Current Location	Status	
Extra Battalion Vehicles				
C863	Shop	Station 12	available	Battalion 4 when needed
Extra Medics			No Medic Units	
M900	Shop	M4	I/S	repairs
M903	Shop	Shop	O/S	air brake leak
M904	Shop	M18	O/S	M18 904 O/S
M911	Shop	M19	I/S	park brake issue (990)
M995	Shop	Shop	O/S	cab floor issue
M993	Shop	Shop	O/S	at delaership
M992	Shop	M18	I/S	repairs
EXTRA APPARATUS REPORT				
Date	9/17/2025	Shift		Comments
Rig #	Home Station	Current Location	Status	
Extra Battalion Vehicles				
C863	Shop	Station 12	available	Battalion 4 when needed
Extra Medics				
M900	Shop	Shop	O/S	at dealership
M903	Shop	Shop	O/S	air brake leak
M904	Shop	M18	I/S	NO REAR A/C (966)
M911	Shop	M19	I/S	park brake issue (990)
M995	Shop	Shop	O/S	cab floor issue

M993	Shop	Shop	O/S	at delaership
M992	Shop	Shop	O/S	at dealership

EXTRA APPARATUS REPORT

Date	9/16/2025	Shift		
Rig #	Home Station	Current Location	Status	Comments
Extra Battalion Vehicles				
C863	Shop	Station 12	available	Battalion 4 when needed
Extra Medics				
M900	Shop	Shop	O/S	at dealership
M903	Shop	Shop	O/S	air brake leak
M904	Shop	M18	I/S	NO REAR A/C (966)
M911	Shop	M19	I/S	park brake issue (990)
M995	Shop	Shop	O/S	cab floor issue
M993	Shop	Shop	O/S	at delaership
M992	Shop	Shop	O/S	at dealership

EXTRA APPARATUS REPORT

Date	9/15/2025	Shift		
Rig #	Home Station	Current Location	Status	Comments
Extra Battalion Vehicles				
C863	Shop	Station 12	available	Battalion 4 when needed
Extra Medics				
M900	Shop	Shop	O/S	at dealership
M903	Shop	Shop	O/S	air brake leak
M904	Shop	M18	I/S	NO REAR A/C (966)
M911	Shop	M19	I/S	park brake issue (990)
M995	Shop	Shop	O/S	cab floor issue

M993	Shop	Shop	O/S	at delaership
M992	Shop	Shop	O/S	at dealership

EXTRA APPARATUS REPORT

Date	9/10/2025	Shift		
Rig #	Home Station	Current Location	Status	Comments
Extra Battalion Vehicles				
C863	Shop	Station 12	available	Battalion 4 when needed
Extra Medics				
M900	Shop	CEP	available	at the CEP
M903	Shop	Shop	O/S	air brake leak
M904	Shop	M18	I/S	NO REAR A/C (966)
M911	Shop	M19	I/S	park brake issue (990)
M995	Shop	M4	I/S	Body mounts broken (999)
M993	Shop	Shop	O/S	engine issue
M992	Shop	Shop	O/S	cab floor issue

EXTRA APPARATUS REPORT

Date	9/9/2025	Shift		
Rig #	Home Station	Current Location	Status	Comments
Extra Battalion Vehicles				
C863	Shop	Station 12	available	Battalion 4 when needed
Extra Medics				
M900	Shop	CEP	available	at the CEP
M903	Shop	Shop	O/S	air brake leak
M904	Shop	M18	I/S	NO REAR A/C (966)
M911	Shop	M19	I/S	park brake issue (990)
M995	Shop	M4	I/S	Body mounts broken (999)

M993	Shop	Shop	O/S	engine issue
M992	Shop	Shop	O/S	cab floor issue
EXTRA APPARATUS REPORT				
Date	9/8/2025	Shift		
Rig #	Home Station	Current Location	Status	Comments
Extra Battalion Vehicles				
C863	Shop	Station 12	available	Battalion 4 when needed
Extra Medics				
M900	Shop	CEP	available	at the CEP
M903	Shop	Shop	O/S	air brake leak
M904	Shop	M18	I/S	NO REAR A/C (966)
M911	Shop	M19	I/S	park brake issue (990)
M995	Shop	M4	I/S	Body mounts broken (999)
M993	Shop	Shop	O/S	engine issue
M992	Shop	Shop	O/S	cab floor issue